

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 501

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 501 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 502

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 502 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 509

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 509 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 510

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 510 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 516

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 516 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 517

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 517 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 518

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 518 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 519

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 519 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 540

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 540 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 542

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 542 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 543

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 543 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 544

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 544 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 545

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 545 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 546

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 546 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 547

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 547 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 548

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 548 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 549

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 549 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 550

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 550 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 551

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 551 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 552

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 552 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager

11 Aug 2022

TO WHOM IT MAY CONCERN

Re: Kerani Heights Stage 5
Melton
Lot 553

Terra Firma Laboratories was engaged by Ginsan Construction Pty Ltd as the Geotechnical and Inspection Testing Authority (GITA) to provide Level 1 supervision and testing on the earthworks component for Kerani Heights, Stage 5, Melton in accordance with Australian Standard AS3798 Guidelines for Earthworks for Commercial and Residential Development.

Lot 553 as defined in drawing Ref 305874CR200 from *Potter George*, provided by the contractor, was included in the scope of works.

With regard to any fill placement please consider the following:

- Controlled fill was placed up to 300mm below finished surface level. The final 300mm fill is considered top soil and organic matter and not controlled fill.
- Verification of finished surface level to design levels is outside of the scope of the GITA Inspection and Verification report.
- Compaction tests results documented in a level 1 GITA report verify the construction methods observed on site are satisfactory. Testing is conducted with random sampling across an area of work that is defined in the Australian Standard as a "lot" which is "an area of work that is essentially homogenous in relation to material type and moisture condition, rolling response and compaction technique, and which has been used for the assessment of the relative compaction of an area of work" (AS 3798-2007). As such, any test completed is representative of an area that may be up to 2500m² in area and across several house lots.

A GITA Inspection Verification report (Reference: D21706A) has been published on 11 Aug 2022 and documents that the allotment earthworks were carried out in accordance with AS3798 and in compliance with the project specification provided by the contractor.

For and on behalf of

Terra Firma Laboratories



C Caulfield
Project Manager